

2020 Suzuki Every Van Join		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE HBD-DA17V	DISPLACEMENT 658 cc		
YEAR / REG. 2020/08	MILEAGE 105,940 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. DA17V-481995	DIMENSIONS (L X W X H) 340 × 148 × 190 cm		
SALES POINTS			
Alloy Wheels Navigation System		Pre-Collision Braking	
INSPECTOR REPORT			
Interior dirty, inner pillar bulge/distortion, back panel dent, undercarriage rust (level 2)			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 8月		メーカー スズキ		ドア枚数 5	ボディ形状 軽四	軽価値 3.5																																																										
車名 エブリー		グレード ジョイン		駆動区分 4WD																																																												
車種 自家用・その他 ()	排気量 660	型式 HBD-DA17V	通称 型式	内装 A・B・⑨																																																												
年 月 日	燃料 軽油	ディーゼル	後付選り品 (保証書・取扱説明書等)																																																													
走行 105,940 km	シフト AT																																																															
外装色 ホワイト	カラーNo. ()	エアコン ()	装備品のみ O印 を記入																																																													
内装色 ()	乗車定員 人	サンルーフ	革シート																																																													
左・前・後	ディーラー	走行	リサイクル料	8,400円	エブリック	TV キーレス																																																										
セールスポイント																																																																
検査記入欄 書類送付は成約後10日後かかります。 室内汚れ ビラーインナーBU バックパネルU 下回りC2 <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> <tr> <td colspan="9">登録No. 月 日 までに名実できる方</td> </tr> <tr> <td colspan="9">車体番号 DA17V-481995</td> </tr> <tr> <td>FW</td><td>①</td><td>②</td><td>③</td><td>④</td><td>⑤</td><td>⑥</td><td>⑦</td><td>⑧</td><td>⑨</td> </tr> <tr> <td>内装</td><td>⑩</td><td>⑪</td><td>⑫</td><td>⑬</td><td>⑭</td><td>⑮</td><td>⑯</td><td>⑰</td><td>⑱</td> </tr> </table>							A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/サケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録No. 月 日 までに名実できる方									車体番号 DA17V-481995									FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	内装	⑩	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/サケ	G	ガラスキズ																																																							
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																																																							
登録No. 月 日 までに名実できる方																																																																
車体番号 DA17V-481995																																																																
FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨																																																							
内装	⑩	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱																																																							