

|                                                                                                                                                    |                                              |                   |          |
|----------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------|----------|
| 2020 Toyota Passo X L Package S                                                                                                                    |                                              | OVERALL           |          |
|                                                                                                                                                    |                                              | 4.5               |          |
|                                                                                                                                                    |                                              | EXTERIOR          | INTERIOR |
|                                                                                                                                                    |                                              | -                 | -        |
| MODEL CODE<br>M700A                                                                                                                                | DISPLACEMENT<br>996 cc                       |                   |          |
| YEAR / REG.<br>2020/07                                                                                                                             | MILEAGE<br>49,989 km                         |                   |          |
| DOORS<br>5                                                                                                                                         | SEATS<br>5                                   |                   |          |
| DRIVETRAIN<br>2WD (FF)                                                                                                                             | TRANSMISSION<br>AT                           |                   |          |
| FUEL<br>Petrol                                                                                                                                     | STEERING<br>Right                            |                   |          |
| EXTERIOR COLOR<br>Other                                                                                                                            | BODY TYPE<br>Hatchback                       |                   |          |
| CHASSIS NO.<br>M700A-0164169                                                                                                                       | DIMENSIONS (L X W X H)<br>365 × 167 × 153 cm |                   |          |
| SALES POINTS                                                                                                                                       |                                              |                   |          |
| Pre-Collision Braking                                                                                                                              |                                              | Navigation System |          |
| INSPECTOR REPORT                                                                                                                                   |                                              |                   |          |
| Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. No structural damage. |                                              |                   |          |

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

|                     |                   |                   |                       |            |
|---------------------|-------------------|-------------------|-----------------------|------------|
| 初年度登録<br>R2/7月      | メーカー<br>トヨタ       | ドア枚数<br>5         | ボディ形状<br>コンパクト/ハッチバック | 評価点<br>4.5 |
| 車名<br>パッソ           | グレード<br>X LパッケージS |                   |                       |            |
| 車種<br>自家用           | 型式<br>M700A       | 総排気量<br>1000      | 燃料<br>ガソリン            | 内装<br>B    |
| 車検<br>- - 年 月 / 期   | 走行<br>49,989 km   | 価格<br>8,190 円     | 車台番号<br>M700A-0164169 | 重量<br>Kg   |
| 外装色<br>ブラックマイカメタリック | カラーNo.<br>( )     | リサイクル料<br>8,190 円 | 車検<br>AC              | 長さ<br>cm   |
| シフト<br>インパネ         | AT                | 5 人               | 高さ<br>cm              | cm         |

後付品  
(保証書・取扱説明書等)

装備  
AW サルーフシート  
TV キーレス

セールスポイント  
バックカメラ/ETC/横滑り防止装置(E S C)/運転席エアバック/後部座席シートベルト/スマートキー/キーレスエントリー/A B S/助手席エアバック/メモリーナビ/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/パナセー

査定員記入欄

※ダメージレベルに関する注意事項  
ダメージレベルは1から5まであり、1が最も軽微なダメージ、5が最も重大なダメージを示します。本車はダメージレベル1で、軽微なダメージのみです。

クオリティグレード説明  
外装: 軽微なキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。  
内装: 軽微な汚れ等が、部分的にあります。  
修復歴: 骨格部位に異常はありません。

車両状態の説明  
車両状態の説明は、写真と併せて記載されています。