

2020 Toyota Probox Van GL		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE NSP160V		DISPLACEMENT 1,329 cc	
YEAR / REG. 2020/01		MILEAGE 28,360 km	
DOORS 5		SEATS 5	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR White		BODY TYPE Minivan	
CHASSIS NO. NSP160V-0049853		DIMENSIONS (L X W X H) 425 × 169 × 153 cm	
INSPECTOR REPORT			
Exterior 4 stars, Interior 4 stars. Scratches on door knobs, headliner, other trim, steering wheel, and around key cylinder. Small scuffs and stains on dashboard. Wrinkles/scratches on driver's seat interior trim. Scuffs and stains on rear seat back.			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 1月		メーカー トヨタ		ドア枚数 5		ボディ形状 バン		評価点 4	
		車名 プロボックス		グレード GL		JAAA鑑定車			
車歴 自家用・その他 ()		排気量 1300 CC		型式 NSP160V		通称 型式		A・B・C	
車検 - - 年 / 月 / 日		燃料 ガソリン		ディーゼル		後日選り品 ()			
走行 28,360 km		シフト フロア		AT					
外装色 ホワイト		カラーNo. ()		エアコン AC・C・WAG・()		新車定員 人		AW サンルーフ 革シート	
ハンドル 左・右		輸入 区分		ディーラー ・ 並行		7,440円		エアバック ナビ TV	
セールスポイント CD/E TC/運転席エアバック/キーレスエントリー/ABS/ 衝突被害軽減ブレーキ/スペアキー									
検査記入欄 外装★4内装★4 A.AUは複数個を意味します。ドアノブ きず 天張りしわすれきず 他トリムしわすれきず ハンド ルすれきず キーシリンダー周辺きず ダッシュすれきず汚 れ小 D席内張りしわすれきず 後部座席背部すれきず汚れ					修復歴 有 () A キズ U ヘビオサレ B キズヘビ B 色あせボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 XX 交換所 登録No. 月 日 までに名義できる方 車体番号 NSP160V-0049853 PW トピ石 傷A フレ 外装 小 A・B ホイル A・曲 エアロ 内装 3030 シミ ヤブレ コガ コガ穴 オーディ穴				