


2021 Audi Audi A1 Sportback 25 TFSI Advanced		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3BA-GBDKL	DISPLACEMENT 999 cc		
YEAR / REG. 2021/11	MILEAGE 15,938 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE Hatchback		
CHASSIS NO. WAUZZZGB0MR066135	DIMENSIONS (L X W X H) 404 × 174 × 144 cm		
SALES POINTS			
Alloy Wheels Navigation System		Pre-Collision Braking	
INSPECTOR REPORT			
Interior scratches, minor dent (W2), door mirror scratches			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 11月		メーカー アウディ		ドア枚数 5	ボディ形状 コンパクトハッチバック	評価値 4.5																				
車名 A1 スポーツバック		グレード 25 TFSI アドバンスド		駆動区分 2WD	4WD																					
車種 自家用・その他 ()	排気量 1000 CC	型式 3BA-GBDKL	通称 3BA-GBDKL	内装 A・B・C																						
年 15	月 9	日 8	燃料 ガソリン	ディーゼル	後付選り品 ()																					
走行 15,938 km	フロア	AT	配線類																							
外装色 グリーン	カラーNo. ()	エアコン	装備品のみ O印 を記入																							
内装色 ()	乗車定員 5人	サンルーフ	革シート																							
左・前・後 左・前・後	走行 11,370 km	リサイクル料	エコパック	ABS	ESP	モーター																				
セールスポイント 1オーナー車、純正ナビ、TV、Bカメラ、ETC、純正ドライブレコーダー(FR)、LEDヘッドライト、バーチャルコックピット、コンビニエンス&アシスタンスパッケージ、PDC、ナビゲーションパッケージ、ブラインドスポットモニター、スマートキー、プッシュスタート、アダプティブクルーズアシスト、メーカーOPボディカラー (グリーン)																										
検査記入欄 内装キズ、W2、Dミラーキズ			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘビイオサレ</td><td>B</td><td>キズ・ヘビイ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘビイオサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済
A	キズ	U	ヘビイオサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済																	
登録No. WAUZZZGB0MR066135			名義中 月 日 までに変更できる方																							
車体番号 WAUZZZGB0MR066135			シリアルNo. ()																							
FW	トビ	機A	ワレ	外装	小	ホイール	エアロ																			
内装	シロ	ヤブレ	コガ	コガ	コガ	オーディオ	シリアル																			
重量 cm			長さ cm			最大積載量 kg																				