

2021 Audi Audi A6 40TDI quattro sport S line package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3CA-F2DFBF	1,968 cc		
YEAR / REG.	MILEAGE		
2021/06	39,300 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WAUZZZF22MN050138	495 × 189 × 143 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Parking Assist (Auto Steering)		360° Camera	
Navigation System		Audi Sound System (180W, 10 speakers)	
INSPECTOR REPORT			
AIS inspected. Minor scratches on mirrors. Front seats have minor wrinkles, driver's seat has moderate scuffing. Pillar trim and console have minor scuffs. Left fender and left quarter panel show repair marks. Exterior has minor hairline scratches and small scratches. Front bumper has paint repair marks. Minor stone chips on front glass.			

年式登録 R3 / 16月 A 6 アパント		アウディ 車名		ドア仕様 5		ステーションワゴン 車種区分		評価点 4	
車種 自家用・その他 ()		排気量 2000		型式 CC 3CA-F2DFBF		運転形式 内装		A・B ()	
車検 - - 年 月 日		燃料 ガソリン		デザイン グレード		製造国 日本			
走行 0 0 3 9 3 0 0		ナイル フロア 7 AT		製造国 日本					
外装色 ミストブラックメタリック		カラーNo. ()		エキップ ()		新製品のみの印を記入			
()		内装色 ()		5人		サンプル			
左・右 ()		走行 ()		17,230円		エキップ			
セールスポイント									
4ゾーンデッドクサースオートマチックエアコンディショ ナー HDマトリクスLEDヘッドライト S line パークアシストパッケージ パルコナレザー ブラ イバシールガラス									
検査記入欄									
★A I S 検査済 ミラーA フォードL小 運転席座席内 ピア内内小 コンソール小 左フエダ8左クオーター座席 外鏡調整スズ 外鏡小鏡有 F/C/1座席鏡 Fガラス飛び石小									
検査項目 A キズ W 傷損傷 U ハネヒキ等 B 変色・へこみ P 変色・ひび割れ X 交換済 XX 交換済 S サビ C 腐食 H 欠損 A 交換済									
車検 月 日 まで(名義変更有)									
車検 MAUZZZF22MN050138									
車検 MAUZZZF22MN050138									