

2021 BMW BMW 1series BMW 1 Series 1.5 118i DCT		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE 3BA-7K15	DISPLACEMENT 1,499 cc		
YEAR / REG. 2021/05	MILEAGE 15,298 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. WBA7K320807J12038	DIMENSIONS (L X W X H) 433 × 180 × 146 cm		
SALES POINTS			
Alloy Wheels Back Camera		Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches, dents, and repair marks. Wheels are scratched. Various trim parts, seats, console, and cargo area show wrinkles, scuffs, scratches, and dirt. Tires are cracked. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement. Interior also has burns, holes, tears, and rips.			

初度登録年月 令和3 年 5 月		車名・グレード BMW1シリーズ 118i		2WD 4WD		(4)	
ディーラー・並行 モデル年式 ハンドル 左・右		型式 3BA-7K15		排気量 1500 CC		ドア 5 人 形状 力 積載 5 人 重量 kg	
車種 家用 車検 年 月 (日) 走行 1万5千298 km 色 ホワイト 色替 色コード マイ		シフト FAT 冷房 AAC 燃料 ガソリン		セールスポイント (正常に機能するものに限りです) キーレススマートキー Sロナビ バックカメラ 軽減ブレーキ 装備品 (純正品に限り○をつけてください) (PS) SR (PW) ナビ (ABS) TV (AFB) カワ (AW)			
R券 17,680 円		新車保証書 後日届 有・ 無					
注意事項申告欄 外装 小A・小U 外装補修跡表 ホイール キズ デンパバシワスレキズ トリムシワスレキズ シートシワスレ コンソールスレキズヨゴレ 荷室スレキズヨゴレ タイヤヒビキレ							
フロントガラス キズ・傷・ヒビ割・リペア跡・X要 内装 キズ・汚レ・ヨゴレ・穴・スレ・キレ・破レ							
車台番号 07J12038 登録番号							
型式批准番号 国 号 19430 車検 433 年 月 個別区分番号 号 号 0001 車検 180 年 月 車検 146							

検査ポイント図