

2021 BMW BMW 3series Touring 318i Touring		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6K20	1,998 cc		
YEAR / REG.	MILEAGE		
2021/05	16,995 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA72DZ0X0FL15689	472 × 183 × 147 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Tailgate		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Parking Assist (Auto Steering)		Back Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: There are noticeable scratches and dents. Interior: There are some noticeable stains in parts. Repair History: No abnormalities in the frame/structural parts.			

軽年次登録 R/5月 メーカー BMW ドア枚数 5 ボディ形状 ステーションワゴン		評価点 4.5	
車名 3 シリーズ		グレード 3 1 8 ツーリング	
車種 自家用		ディーゼル ☒	右 ☒
年式 16年		走行距離 62K20	年式 2000
車体色 白		車体色 白	車体色 白
外装色 ホワイート		カラー-No. 19560円	車体番号 WBA7ZD2X0F1L5689
内装色 白		シフト フロア 8 AT	車体色 白
走行距離 62K20		年式 2000	車体色 白
車体番号 WBA7ZD2X0F1L5689		車体色 白	車体色 白

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席

☒ 運転席
☒ 助手席
☒ 後座席
☒ 後座席
☒ 後座席