

2021 BMW_Mini BMW Mini Clubman Cooper D Clubman		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3DA-BB20M	DISPLACEMENT 1,995 cc		
YEAR / REG. 2021/12	MILEAGE 31,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Station Wagon		
CHASSIS NO. WMW32BC0202R64177	DIMENSIONS (L X W X H) 428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Sunroof Back Camera	
INSPECTOR REPORT			
Tire cracks, one tire cut, minor scuff on driver's seat, minor A-grade scuff on front door trim, minor A-grade scuff on pillar trim, minor A-grade scuff on cargo area trim, minor scuff on steering wheel, minor front dents, front door repair mark, minor stone chip on glass.			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 12月	MINI	5	ステーションワゴン	4.5
車種 自家用・その他 ()	排気量 2000 cc	型式 3DA-BB20M	内装 A・⑤・C	
車検 8年12月 / 扶養 無し	燃料 ガソリン	変速機 ハンドリフト ()	後付選用品 (保証書・取扱説明書等)	
走行 31,000 km	フロア 8 AT			
外装色 エニグマディック・ブラック・メタリック	カラーNo. ()	エアコン AG・⑤・WAG・()	新選用品のみ・O印を記入	
内装色 ()	乗車定員 5人	PS	サンルーフ	革シート
左・⑤ 輸入車	走行 17,800 km	ナビ付	TV	⑤
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/H D D ナビ/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/L E Dヘッドライト/横滑り防止装置 (ESC) /バックカメラ/障害物センサー/M Tモード付き				
検査記入欄				
タイヤヒビ/タイヤ切れ1本/運転席すれ小/ドア内張A小/ビラー内張A小/荷室内張A小/ハンドルすれ小/フェンダー修理跡/Fガラス飛び石小				
名義中				
月 日 まで名義である方				
WMW32BC0202R64177				
車種	年式	型式	シリアルNo.	登録番号
ミニ	2021	3DA-BB20M	WMW32BC0202R64177	