

2021 BMW_Mini BMW Mini Clubman Cooper D Clubman		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-BB20M	DISPLACEMENT 1,995 cc		
YEAR / REG. 2021/08	MILEAGE 55,381 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Station Wagon		
CHASSIS NO. WMW72BB0902R18557	DIMENSIONS (L X W X H) 428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Back Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Slight interior dirt			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 8月	メーカー MINI MINI	ドア枚数 5	ボディ形状 ステーションワゴン	評価値 4.5
車種 自家用・その他 ()	排気量 2000 CC	型式 3DA-BB20M	通称 3DA	内装 A・B・C
車検 - 年 / 月 / 日	燃料 ガソリン	変速機 AT	後付選り品 ()	
走行 55,381 km	フロア	AT		
外装色 ブラックII	カラーNo. C3Y	エアコン	装備品のみ O印 を記入	
()	内装色	乗車定員 5人	サンルーフ	革シート
左・前・後 左・前・後	走行 17,800円	リサイクル料	エブリック	TV
セールスポイント				
★ワンオーナー★クラシックトリム★ハーフレザーズ ボーズシート★純正ナビ★バックカメラ★前後PDC★デ ジタルメーター★ミラーETC★ACC★ミニドライビング モード★LEDヘッドライト★17インチアルミ★パークア シスト★スマートキー★ドライビングアシスト★パー ジプラス★スベアーキー★R48,5/8,6/7,7/8,記録有★				
検査記入欄				
ルーム内薄汚れ				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 YX 交換品				
登録No. 月 日 までに名義できる方				
車体番号 WMW72BB0902R18557				
FW () 備A フレ 外装 小 大 車体 番号				
内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディオ穴 スレ				