

2021 BMW_Mini BMW Mini Crossover Cooper SD Crossover ALL4		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 42BT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2021/03	MILEAGE 19,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WMW22BU0203M76223	DIMENSIONS (L X W X H) 432 × 182 × 160 cm		
SALES POINTS			
Alloy Wheels Leather Seats Power Seats (Front) Adaptive Cruise Control Navigation System		Roof Rails Power Tailgate Pre-Collision Braking Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 3月	MINI	5	SUV/クロカン	5
MINI	クーパーSD クロスオーバー オール4 AIS検査済	2WD	4WD	
車種 自家用 ・ その他 ()	排気量 2000 cc	型式 42BT20	登録区分 A・⑤・C	
車検 10年 3月 / 扶養 無し	燃料 ガソリン	変速機 ハンドリフト ()	後日選り品 (保証書・取扱説明書 等)	
走行 19,000 km	フロア 8 AT			
外装色 エングマティックブラック	カラーNo. ()	エアコン ()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 5人	サンルーフ	7
左・前・後 18,170円	走行 18,170円	販売店	エレクト	TV
セールスポイント				
本革シート/パワーシート/バックカメラ/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/H D Dナビ/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/ターボ/シートヒーター/電動リアゲート/ミュージックサーバー/ミュージックプレーヤー接続可				
検査記入欄				
修復歴 有・⑥				
A キズ B ハコボネサレ C キズ・ヘコみ D 色あせ・汚れ E ガラスキズ				
W 腐蝕跡 S サビ C 腐食 X 交換部 YX 交換済				
名義中				
月 日 まで名義できる方				
WMW22BU0203M76223				
内装 3色レ	シス	サブレ	コグ	コグス
小	オイル	エアロ	シフト	変速
④	④	④	④	④
cm	cm	cm	cm	kg