

2021 CHRYSLERJEEP JEEP Compass Limited		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3BA-M624	2,359 cc		
YEAR / REG.	MILEAGE		
2021/09	16,954 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MCANJRCB8MFA76247	442 × 181 × 164 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats (Leather)		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Parking Assist (Auto Steering)	
Front Camera		Side Camera	
Back Camera		Navigation System	
Alpine 506W 9-speaker Premium Sound...			
INSPECTOR REPORT			
Interior scratches			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 9月		メーカー クライスラー・ジープ		ドア数 5	ボディ形状 SUV/クロカン	評価点 5																				
車名 ジープ・コンパス		グレード リミテッド		駆動方式 2WD	4WD																					
車種 自家用 ・ その他 ()	排気量 2400 cc	型式 3BA-M624	燃料 ディーゼル	登録区分	A・B・C																					
年 月 日	走行 16,954 km	AT	後付選用品 ()																							
外装色 ブラック	カラーNo.	エアコン	新選用品のみ O印 を記入																							
内装色	乗車定員 人	人	サンルーフ	キーレス																						
左・前・後・右	17,060円	17,060円	エレクト	キーレス																						
セールスポイント																										
プッシュスタート、アルミホイール、全方位カメラ、クルーズコントロール、パワーシート、ナビ/TV																										
検査記入欄																										
内装キズ																										
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘッドライト</td><td>B</td><td>キズ・ヘコ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>雨傷跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>							A	キズ	U	ヘッドライト	B	キズ・ヘコ	P	色あせ・汚れ	G	ガラスキズ	W	雨傷跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	ヘッドライト	B	キズ・ヘコ	P	色あせ・汚れ	G	ガラスキズ																	
W	雨傷跡	S	サビ	C	腐食	X	交換部	XX	交換済																	
登録月 年 月 日 までにご来店ください 車体番号 MCANJ RCB8MFA76247																										
FW	シス	サブレ	コグ	コグス	オーディオ	スレ																				
長さ	幅	高さ	重量	kg																						