

2021 CHRYSLERJEEP JEEP Compass Limited		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE M624	DISPLACEMENT 2,359 cc		
YEAR / REG. 2021/07	MILEAGE 26,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. MCANJRCB8MFA73669	DIMENSIONS (L X W X H) 442 × 181 × 164 cm		
SALES POINTS			
Alloy Wheels Leather Seats Power Seats (Front) Adaptive Cruise Control Back Camera Navigation System		Roof Rails Power Tailgate Pre-Collision Braking Parking Assist (Auto Steering) 360° Camera Premium Sound System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

車種 R3 / 7月	メーカー クライスラー・ジープ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 ジープ・コンパス	グレード リミテッド	駆動方式 2WD	燃費区分 400	
車体 自家用・その他 ()	排気量 2400 cc	型式 M624	登録区分 A・⑤・C	
年 -	月 -	日 -	ディーゼル -	後付選用品 (保証書・取扱説明書等)
走行 26,000 km	フロア 9	AT		
外装色 BRILLIANT BLACK	カラーNo. ()	エアコン ()	安全装置 ()	装備品のみのO印を記入
左・前 ()	右・後 ()	走行 ()	17,060円	オプション ()
セールスポイント				
本革シート/パワーシート/バックカメラ/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/4WD/アイドリングストップ/シートヒーター/電動リアゲート/全周周カメラ/フロントカメラ/サイドカメラ				
検査記入欄				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中				
月 日 まで				
MCANJ RCB8MFA73669				
シリアル No.				
重量				