

2021 Daihatsu Thor Custom Custom G		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-M900S	DISPLACEMENT 996 cc		
YEAR / REG. 2021/08	MILEAGE 27,038 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. M900S-0087703	DIMENSIONS (L X W X H) 371 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 8月		ダイハツ トール		5 カスタムG		コンパクトハッチバック		4.5																					
車種	自家用・その他 ()	排気量	1000 CC	型式	5BA-M900S	通称		内装	A・⑨・C																				
車検	- - 年 / 月 / 日	燃料	ガソリン	エンジン	ディーゼル	後日取り込み () 取替 () 取替 () 等 ()																							
走行	27,038 km	シフト	AT																										
外装色	ブルー	カラーNo.	B86	エアコン	AG・⑨・WAG・ ()	装飾品のみ O印 を記入																							
()	()	内装色		乗車定員	5 人	()	()	()	サンルーフ																				
左・右	左・右	ディーラー	並行	9,720円	・ 預託金	エアロ	()	ナビ	TV																				
セールスポイント 両側パワースライドドア、カロッツェリアディスプレイ、バックカメラ、ETC、OPエアロパーツ付き																													
検査記入欄					修復歴 有・⑨																								
補修跡					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ・サレ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ・サレ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
登録No.					名 変 中																								
月 日					までに名変できる方																								
車検番号					M900S-0087703																								
FW	⑨	備A	フレ	外装	小	ホイル	エアロ	シリアル	No.																				
内装	⑨	シミ	ヤブレ	コガ	コガ穴	オーデ・穴	⑨	車種	cm																				