

2021 Daihatsu Thor X		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M900S	DISPLACEMENT 996 cc		
YEAR / REG. 2021/04	MILEAGE 81,277 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. M900S-0084956	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Left side has repair history, interior has dirt and scuffs, seats have tears, studless tires, missing wheel center cap, left center pillar dent/paint damage.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R3 4月	メーカー ダイハツ 車名 トール	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 R																				
車種 自家用・その他 ()	排気量 1000 CC	型式 5BA-M900S	通称 2WD	内装 A・B																				
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)																					
走行 81,277 km	シフト インパネ	AT																						
外装色 パール	カラーNo. W24	エアコン	装備品のみ O印 を記入																					
()	内装色	5人	PS	AW																				
左・右	ディーラー	走行	9,720円	ABS																				
セールポイント 純正ナビ、フルセグTV、バックモニター、ETC、パワースライドドア、スマートアシスト、ドライブレコーダー (SD欠)																								
検査記入欄 左面修復歴、ルーム内汚れスレ、シートキレ、スタッドレスT、ホイールCP欠、左センターピラーBP			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>		A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No. M900S-0084956			名義中																					
FW			シス																					
ヤブレ			コガ																					
コガ			オーディー																					
車種			長さ																					
cm			cm																					
cm			Kg																					