

2021 ES 300h F Sport		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE AXZH11	DISPLACEMENT 2,487 cc		
YEAR / REG. 2021/01	MILEAGE 58,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. AXZH11-1001787	DIMENSIONS (L X W X H) 498 × 187 × 145 cm		
SALES POINTS			
Alloy Wheels Leather Seats Navigation System		Sunroof Adaptive Cruise Control Lexus ES Premium Sound System (8 Sp...	
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present in parts. No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青森内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R3/1月	メーカー レクサス	ドア数 4	ボディ形状 セダン	評価点 4.5
車種 ES	グレード 300h Fスポーツ	登録年 2500	燃料 ガソリン	内装 B
用途 R3/1月	車名 AXZH11	登録月 5月	走行距離 58,000 km	重量 1,780 kg
外装色 ブラック	カラーNo. 223	リサイクル料 11,790円	車内番号 AXZH11-1001787	
シフト フロア	AT	乗車定員 5人	長さ 498 cm	幅 187 cm

車検返却日
(保証書・取説説明書等)

装備
ABS アイドルストップ テレマチック ナビ TV

セールスポイント

査定員記入欄

※ダメージレベルに関する注意事項
●ダメージレベルは、車検通過の目安です。ダメージレベルが大きい車は、修理費が高くなる可能性があります。また、ダメージレベルが大きい車は、将来的に値下がりが激しい可能性があります。

クオリティグレード説明
外装: 劣化する平ズやヘコミは補修済みですが、小さな平ズやヘコミが残っています。
内装: 劣化する汚れ等が、部分的にあります。

修理歴: 骨格部位に異常はありません。

車検返却の保証は、停止状態で実施できる範囲で行います。