

2021 Honda FIT 1.3 Home		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-GR1	DISPLACEMENT 1,317 cc		
YEAR / REG. 2021/06	MILEAGE 22,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. GR1-1022644	DIMENSIONS (L X W X H) 400 × 170 × 154 cm		
SALES POINTS			
Pre-Collision Braking Back Camera		Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and minor dents. Seat has tears. Front windshield has scratches, stone chips, cracks, and repair marks; replacement is required. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和3 6 月	車名・グレード フィット ホーム	2WD 4WD (4)	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 6BA-GR1	排気量 1300 CC	ドア 5 形状 HB 定員 5人 積載 kg
車歴 自家用	シフト CVT	セールスポイント (正常に機能するものに限ります)	
車検 令和8 年 6 月 (日)	冷房 AAC	キーレススマートキー・安全ETC・カメラバックモニター	
走行 2万 1千 600 km	燃料 ガソリン	装備品 (純正品に限り○をつけてください)	
色 レッド2	色替 R565MA	(PS) SR	(PW) ナビ
R券 8,950 円		(ABS) (TV)	(エアB) カワ
注意事項申告欄		AW	
外装 小A・小U		新車保証書 有・無	後日品
シート 切れ			
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・(キズ)・破レ	スケア	
車台番号 1022644	登録番号 名変中	A-キズ E-エケボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
		型式指定番号 登録年月 車検年月	類別区分番号 登録年月 車検年月

