

2021 Honda FIT 1.5 e:HEV Lux		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6AA-GR3	1,496 cc		
YEAR / REG.	MILEAGE		
2021/01	46,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GR3-1040814	400 × 170 × 154 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Leather)	
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Light dirt and scratches in the interior, steering wheel wear, seat wrinkles.			

初年度登録 R3 / 1月		メーカー ホンダ		ドア枚数 5		ボディ形状 コンバット/ハッチバック		評価点 4.5																					
車種 自家用・その他 ()		排気量 1500 CC		型式 6AA-GR3		国産車 ☒		内装 A・B・C																					
車検 10 年 1 月 / 扶消		数量 ガソリン バッテリー ()		ディーゼル シフト		後日送り品 ()		買取相場表 ()																					
走行 口内・ノック・内装・外装・エンジン・ボディ・タイヤ・ホイール 46,000		フロア AT																											
外装色 ブラチナホワイト・パール ()		カラーNo. ()		エンジン Q6・AGD・WAD・()		新車品のみ O印 を記入																							
()		内装色 ()		車検年度 5 人		☒ ☒ ☒ ☒ ☒		サンプル 革シート																					
シロ 左・()		輸入 国産		ディーラー ()		走行 ()		シロ ()																					
セールスポイント		プライマル料 8,950円		買取額 ()		エアーク ()		()																					
純正9インチナビ Bカメラ LEDライト スマートキー ETC ハーフレザー コーナーセンサー ホンダセンシング																													
検査記入欄		有 ()																											
ルーム内薄汚れキズ ハンドルスレ シートシワ		<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ/キズ</td> <td>B</td> <td>キズ・へこみ</td> <td>P</td> <td>色あせ/セリ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>傷跡</td> <td>S</td> <td>サビ</td> <td>O</td> <td>変色</td> <td>X</td> <td>交換</td> <td>XX</td> <td>交換済</td> </tr> </table>								A	キズ	U	へこみ/キズ	B	キズ・へこみ	P	色あせ/セリ	G	ガラスキズ	W	傷跡	S	サビ	O	変色	X	交換	XX	交換済
A	キズ	U	へこみ/キズ	B	キズ・へこみ	P	色あせ/セリ	G	ガラスキズ																				
W	傷跡	S	サビ	O	変色	X	交換	XX	交換済																				
車検No.		月 日 までに各店へ送る																											
車体番号 GR3-1040814		車検 年 月 日																											
内装 シロ		車検 年 月 日																											