

2021 Honda FIT Home		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 6BA-GR1	DISPLACEMENT 1,317 cc		
YEAR / REG. 2021/09	MILEAGE 32,309 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. GR1-1103913	DIMENSIONS (L X W X H) 400 × 170 × 154 cm		
SALES POINTS			
Pre-Collision Braking Back Camera		Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Light interior stains			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 9月		ホンダ		5		コンパクトハッチバック		4.5																					
フィット		ホーム		4WD																									
車種	白車用・その他 ()	排気量	1300 CC	型式	6BA-GR1	通称		内装	A・③・C																				
車検	-	年		月		燃料	ガソリン	ディーゼル																					
走行	32,309 km	フロア	AT	後付選り品 (保証書・取扱説明書 等)																									
外装色	パール	カラーNo.	(NH902PX)	エアコン	AG・AG・WAG・()	装備品のみ O印 を記入																							
内装色	()	乗車定員	5人	AW	サンルーフ	革シート																							
左・前	ディーラー	走行	リサイクル料	9,350円	エブリック	③	④	⑤	⑥																				
セールスポイント																													
★ホンダセンシング★メーカー9インチナビ★フルセグTV★バックカメラ★ビルトインETC★スマートキー★ブッシュスタート★ハーフレザーシート★アイドリングストップ★クリアランスソナー★ステアリングスイッチ★LEDヘッドライト★スタッドレスタイヤ★ドライブレコーダー★					修復歴 有・③																								
検査記入欄					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラス/キズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラス/キズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラス/キズ																				
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済																				
ルーム内薄汚れ					登録No. _____ 月 _____ 日 _____ までに変更できる方 名義中 車体番号 GR1-1103913 シリアル No. _____ 車種 _____ 年 _____ 月 _____ 日 _____ 最大積載量 _____ kg																								
FW	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪																				
内装	ヨコレ	シミ	ヤブレ	コガ	コガ穴	オーディー穴	スレ	傷	最大積載量																				