

2021 Honda N-BOX CUSTOM L		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2021/05	18,424 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Brown	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-5015233	340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable dirt is present in parts. Repair history: No abnormalities in the frame.			

青森市内のクーラ鑑定/JAAN鑑定証の評価と下配定価の評価は異なります

初年度登録 R3	メーカー ホンダ	ドアカ数 5	ボディ形状 軽四	評価点 4
月 5	車名 N-BOXカスタム	グレード L		
種別 自家用	型式 右	JF3	排気量 660	燃料 ガソリン
年式 10 年 4 月	抹消	(JF3にマークを記入し、左：価格・右：送料)マイル 18,424km	エアコン AC	安全装置 標準装備
外装色 ブラウン	カラーNo. ()	リサイクル料 ()	車両番号 JF3-5015233	
()	内装色 ()	シフト フロア AT	長さ cm	高さ cm

旅行口送り
(保証書・取扱説明書等)

装備

③	④	⑤	⑥	⑦	⑧	⑨	⑩
ナビ	BS	⑪	TV	⑫	⑬	⑭	⑮

セル&ポイント

後席 両側電動スライド ナビ B
luetooth LED バック
カメラ 前後シートヒーター レー
ダークルーズコントロール 衝突警
戒ブレーキ 障害物センサ

指定員記入欄

※ダメージレベルに関する注意事項

最小は記号のみ
小傷1
小傷2
中傷1
大傷3

例
窓ガラス破損 → A
へこみ小傷1 → L
塗装剥がれ → E2
窓ガラス破損 + へこみ小傷1 → AL3

W	H	前	フル	A	イ	イ	E	AL3
W	H	前	フル	A	イ	イ	E	AL3

クオリティグレード説明

外装色になるズブやヘコミは補修済みですが、小さなズブやヘコミが残っています。

内装色になる汚れ等が、部分的にあります。

修復歴=汚損部位に異常はありません。

車両状態確認シート、廃止記載で実施する検査を行っています。