

2021 Honda Vezel Hybrid e:HEV Z		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 6AA-RV5	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/11	MILEAGE 44,163 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. RV5-1020706	DIMENSIONS (L X W X H) 434 × 179 × 159 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control		Leather Seats Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Damage on both left and right sides, repaired. Dashcam SD card missing. Right front door replaced, left rear door replaced. Lower part of both left and right center pillars are distorted.			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 11月		メーカー ホンダ		ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 3.5
車名 ヴェゼル		グレード e:HEV Z		駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 1500 cc	型式 6AA-RV5	通称 型式	内装 A・B・C		
車検 - - 年 月	燃料 ハイブリッド	ディーゼル	後付部品 () 車・取付説明書 ()			
走行 44,163 km	シフト AT					
外装色 パール	カラーNo. (NH902P)	エンジン AG・AGC・WAG ()	装備品のみ O印 を記入			
左・右・前・後・全周 ()	内装色	乗車定員 5 人	ABS	サンルーフ	キーレス	
走行 11,740 km	ディーラー・走行	11,740 km	エアバック	ABS	キーレス	
セールスポイント						
純正ナビ、フルセグTV、バックモニター、ETC、LED、ハーフレザー、パドルシフト、ホンダセンシング、パワーバックドア、前後ドライブレコーダー			修復歴 有 ()			
検査記入欄 左右損傷あり、補修、ドラレコSD欠、右FドアXX、左RドアXX、左右センターピラー下部ヒズミ			A キズ B ハミ・凹み C 腐食 D 変色 E 変形 F 変質 G 変質 H 変質 I 変質 J 変質 K 変質 L 変質 M 変質 N 変質 O 変質 P 変質 Q 変質 R 変質 S 変質 T 変質 U 変質 V 変質 W 変質 X 変質 Y 変質 Z 変質 名義中 月 日 までに名義できる方 RV5-1020706			
内装	シロ	ヤブ	コガ	コガ	オーディ	オーディ