

| 2021 Honda Vezel Hybrid e:HEV Z                                                                                                                                                                                   |                                              | OVERALL                                                        |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------|----------|
|                                                                                                                                                                                                                   |                                              | 4.5                                                            |          |
|                                                                                                                                                                                                                   |                                              | EXTERIOR                                                       | INTERIOR |
|                                                                                                                                                                                                                   |                                              | -                                                              | -        |
| MODEL CODE<br>RV5                                                                                                                                                                                                 | DISPLACEMENT<br>1,496 cc                     |                                                                |          |
| YEAR / REG.<br>2021/07                                                                                                                                                                                            | MILEAGE<br>40,189 km                         |                                                                |          |
| DOORS<br>5                                                                                                                                                                                                        | SEATS<br>5                                   |                                                                |          |
| DRIVETRAIN<br>2WD (FF)                                                                                                                                                                                            | TRANSMISSION<br>AT                           |                                                                |          |
| FUEL<br>Hybrid (Petrol)                                                                                                                                                                                           | STEERING<br>Right                            |                                                                |          |
| EXTERIOR COLOR<br>Brown                                                                                                                                                                                           | BODY TYPE<br>SUV                             |                                                                |          |
| CHASSIS NO.<br>RV5-1012153                                                                                                                                                                                        | DIMENSIONS (L X W X H)<br>433 × 179 × 159 cm |                                                                |          |
| SALES POINTS                                                                                                                                                                                                      |                                              |                                                                |          |
| Alloy Wheels<br>Pre-Collision Braking<br>Back Camera                                                                                                                                                              |                                              | Power Tailgate<br>Adaptive Cruise Control<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                                                                                                  |                                              |                                                                |          |
| Exterior: Major scratches and dents have been repaired, but small scratches and dents remain.<br>Interior: Some noticeable dirt, etc., is partially present. Repair history: No abnormalities in the frame parts. |                                              |                                                                |          |

[illegible]