

2021 Jeep Compass Limited		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
M624	2,359 cc		
YEAR / REG.	MILEAGE		
2021/11	28,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MCANJRCBXMFA79568	442 × 181 × 164 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Parking Assist (Auto Steering)	
Back Camera		Front Camera	
360° Camera		Navigation System	
Premium Sound System			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 11月		クライスラー・ジープ		5	SUV/クロカン		評価点																				
		ジープ・コンパス		リミテッド			4.5																				
車種	白車用 ・ その他 ()	排気量	2400 cc	型式	M624	内装	A ・ ⑤ ・ C																				
車検	- - 年 / 月 / 日	燃料	ガソリン	ディーゼル	後日選用品 (保証書・取扱説明書等)																						
走行	28,000 km	フロア	フロア 9 AT																								
外装色	BRIGHT WHITE C/C	カラーNo.		エアコン	新選用品のみ、O印を記入																						
内装色		乗車定員	5人	AW	サンルーフ	キーレス																					
左・前・後・右	左・前・後・右	走行	17,060円	エレクトロニクス	TV	キーレス																					
セールスポイント																											
本革シート/パワーシート/バックカメラ/ETC/運転席エアバック/助手席エアバック/4WD				修復歴 有、⑥																							
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サビ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/汚れ</td><td>G</td><td>ガラス/キズ</td> </tr> <tr> <td>W</td><td>雨漏り</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/サビ	B	キズ/ヘコみ	P	色あせ/汚れ	G	ガラス/キズ	W	雨漏り	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サビ	B	キズ/ヘコみ	P	色あせ/汚れ	G	ガラス/キズ																		
W	雨漏り	S	サビ	C	腐食	X	交換済	XX	交換済																		
				名義中																							
				月 日 までにご名義できる方																							
				MCANJRCBXMFA79568																							
内装	トビ石	傷A	フレ	外装	小	ホイール	エアロ	シフト	No.																		
内装	ゴゴレ	シミ	ヤブレ	コガ	コガ	オーディオ	スレ	車検	cm																		