

| 2021 SUBARU Levorg STI Sports EX                                                                                                                                         |                        | OVERALL                 |          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------|----------|
|                                                                                                                                                                          |                        | EXTERIOR                | INTERIOR |
|                                                                                                                                                                          |                        | -                       | -        |
| MODEL CODE                                                                                                                                                               | DISPLACEMENT           |                         |          |
| VN5                                                                                                                                                                      | 1,795 cc               |                         |          |
| YEAR / REG.                                                                                                                                                              | MILEAGE                |                         |          |
| 2021/04                                                                                                                                                                  | 70,821 km              |                         |          |
| DOORS                                                                                                                                                                    | SEATS                  |                         |          |
| 5                                                                                                                                                                        | 5                      |                         |          |
| DRIVETRAIN                                                                                                                                                               | TRANSMISSION           |                         |          |
| 4WD                                                                                                                                                                      | AT                     |                         |          |
| FUEL                                                                                                                                                                     | STEERING               |                         |          |
| Petrol                                                                                                                                                                   | Right                  |                         |          |
| EXTERIOR COLOR                                                                                                                                                           | BODY TYPE              |                         |          |
| Silver                                                                                                                                                                   | Station Wagon          |                         |          |
| CHASSIS NO.                                                                                                                                                              | DIMENSIONS (L X W X H) |                         |          |
| VN5-023046                                                                                                                                                               | 476 × 180 × 150 cm     |                         |          |
| SALES POINTS                                                                                                                                                             |                        |                         |          |
| Alloy Wheels                                                                                                                                                             |                        | Leather Seats (Leather) |          |
| Power Tailgate                                                                                                                                                           |                        | Power Seats (Front)     |          |
| Pre-Collision Braking                                                                                                                                                    |                        | Adaptive Cruise Control |          |
| Cruise Control                                                                                                                                                           |                        | Front Camera            |          |
| Side Camera                                                                                                                                                              |                        | Back Camera             |          |
| Navigation System                                                                                                                                                        |                        |                         |          |
| INSPECTOR REPORT                                                                                                                                                         |                        |                         |          |
| Exterior: There are noticeable scratches and dents. Interior: There are some noticeable stains, etc., in parts. Repair History: No abnormalities in the frame structure. |                        |                         |          |

[illegible]