

2021 MAZDA Carol 5D GF		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/04	MILEAGE 44,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Kei		
CHASSIS NO. HB36S-130215	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show wear and wrinkles. Exterior has minor and light scratches. Vehicle has an AA rating of 4.5. Underbody painted.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3		メーカー マツダ		ドア枚数 5		ボディ形状 軽四		評価点 4.5																					
車名 キャロル		グレード GF		駆動区分 2WD 4WD																									
車歴 自用・その他 ()	排気量 660	型式 CC	HB36S		通称 型式	内装 A・B・C																							
車検 10年4月 / 抹消	燃料 ガソリン	ディーゼル	ハイブリッド ()		後日送り品 (保証書・取扱説明書等)																								
走行 44,000マイル	シフト フロア 5 MT																												
外装色 フィズブルーパールメタリック	カラーNo. ()	エアコン	A・B・AAG・WAG・()		新備品のみ O印 を記入																								
内装色 ()	乗車定員 4人	AW	サンルーフ	革シート																									
左・右 ディーラー・並行	リサイクル料 8,420円・預託金	エアバック	ABS	ナビ	TV	その他																							
セールスポイント ワンオーナー/CD/TTC/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/キーレスエントリー/A B S /助手席エアバック/衝突安全ボディ/ミュージックプレイヤー接続可																													
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4.5点仕入れ 下廻りベイント																													
修復歴 有 ()																													
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>										A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
登録No. HB36S-130215																													
車体番号 HB36S-130215																													
シリアル No.																													
長さ cm 幅 cm 高さ cm 最大積載量 Kg																													