

2021 MAZDA Carol 5D GS 4WD		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/05	MILEAGE 41,366 km		
DOORS 5	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. HB36S-602388	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior dirty, seat scuffs, underbody rust and minor corrosion, core support lower crack, front bumper lower stay crack, front fender liner bent.			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 5月		メーカー マツダ		ドア枚数 5		ボディ形状 ステーションワゴン		評価点 3.5	
		車名 キャロル		グレード GS 4WD		駆動方式 2WD 4WD			
車種 自家用・その他 ()	積気量 660	型式 5BA-HB36S	燃料 ガソリン	ディーゼル	燃料 ハイブリッド ()	燃料 シフト	燃料 ディーゼル	燃料 ハイブリッド ()	燃料 ディーゼル
走行 41,366	走行 マイル	インパネ	AT	走行 マイル					
外装色 シルバー	カラーNo. Z2S	エンジン AG・6AG・WAG ()	整備記録 4人						
左・右		ディーラー	走行	8,420円	税別	登録	AW	サンルーフ	車シート
セールスポイント		シートヒーター コーナーポール 修復歴 有・無							
検査記入欄		室内よごれ シート汚れ 下回りサビ・小腐食 コアサポート下断れ Fバンパー下ステー断れ Fフエンダーライナー曲がり							
FW		トビ石	傷A	フレ	外装	小	ホイール	エアロ	シリアル
内装		シス	ヤブレ	コガ	コガ	オーディオ	車輪	長さ	幅