

2021 MAZDA Carol 5D GS		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/06	MILEAGE 19,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Silver		
BODY TYPE Kei			
CHASSIS NO. HB36S-601899	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior small and light scratches, purchased with AA rating 4.5 points, trim scratches.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 R3 / 6月	メーカー マツダ 車名 キャロル グレード GS	ドア枚数 5 駆動形式 軽四	評価点 4.5
車種 自家用・その他 ()	排気量 660 CC	型式 HB36S	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後付部品 (保証書・取扱説明書 等)
走行 19,000 km	インパネ	AT	
外装色 シルキーシルバームエタリック	カラーNo. QB・AAG・WAG・()	エアコン	装備品のみ ORP を記入
()	内装色	乗車定員 4 人	PS
左・右 左・右	輸入 ディーラー・並行	リサイクル料 8,420 円・預託料	エアバック
セールスポイント			
バックカメラ/TC/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/キーレスエントリー/ABS /助手席エアバック/メモリーナビ他/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター			
検査記入欄			
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4.5点仕入れ トリムキズ			
修理歴 有・無			
A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換車 XX 交換済			
登録No. 月 日 までにも売れる方			
車体番号 HB36S-601899			
FW トビキ 傷A フレ 外装 小 ホイール エアロ B・C A・曲 A・フレ			
内装 3コシ シス ヤブレ コガ コガ穴 オーディオ穴			
長さ 幅 高さ 最大積重量 cm cm cm Kg			