


2021 MAZDA Carol 5D GS Sensor Brake ETC Rear Sonar Seat Heater		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/10	MILEAGE 149,759 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. HB36S-603460	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
INSPECTOR REPORT			
Exterior: Small scratches. Interior: Small scratches, light dirt.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 10月		メーカー マツダ		ドア枚数 5	ボディ形状 軽四	評価点 4																				
車名 キャロル		グレード GS・センサブレーキ・ETC・リアソナー・シートヒーター		駆動区分 2WD 4WD																						
車歴 自家用 ・ その他 ()	排気量 660 CC	型式 HB36S	通称 型式	内装 A ・ B ・ C																						
車検 8年10月 / 抹消	燃料 ガソリン	ディーゼル	後日選り品 (色紙等 ・ 取扱説明書 等)																							
走行 149,759マイル	シフト インパネ	AT																								
外装色 シルバー	カラーNo. ()	エアコン AG ・ AGC ・ WAG ・ ()	装備品のみ O印 を記入																							
内装色 ()	色紙等は10内に「色紙」と記入	乗車定員 4人	AW	サンルーフ	革シート																					
ハンドル 左 ・ (安)	輸入 区分	ディーラー	並行	リサイクル料 8,420円 ・ 預託無	エアバック	ナビ																				
セールスポイント ★デュアルセンサブレーキサポート★キーレス★スベアキー★アイドリングストップ★リアソナー★ETC★シートヒーター★オートエアコン★ディーラー車検記録簿1枚★電動格納ミラー★フロアマット★ドアバイザー★ユーザー買取車★買取店出品																										
検査記入欄 ■ 外装 小キズ ■ 内装 小キズ・薄汚れ			修復歴 有 () <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ・サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	ヘコみ・サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済																	
			登録No. 尾張小牧 581 つ 8286 名実中 月 日 までに名実できる方 車体番号 HB36S-603460																							
FW	トビ石	備A	フレ	外装	小 A ・ U	ホイール A ・ 曲	エアロ A ・ フレ	シリアル No.																		
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	長さ cm	幅 cm																	
								高さ cm	最大積載量 Kg																	