


2021 Mazda CX-3 15S		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-DKLFW	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/08	MILEAGE 40,233 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. DKLFW-107829	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Back Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Light dirt inside the cabin			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 8月		マツダ		5	コンパクトハッチバック		4.5																						
C X - 3		1 5 S		4WD																									
車種	自家用・その他(レンタカー)	排気量	1500 CC	型式	5BA-DKLFW	通称		内装	A・③・C																				
年	2021	月	8	燃料	ガソリン	ディーゼル	後日選り品 (③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺)																						
走行	40,233 km	フロア	AT	整備品のみ O印 を記入																									
外装色	ブラック (41W)	カラーNo.	(41W)	エアコン	④	⑤	⑥	⑦	⑧																				
内装色		乗車定員	5 人	⑨	⑩	⑪	⑫	⑬	⑭																				
左・前	ディーラー	走行	9,200 円	⑮	⑯	⑰	⑱	⑲	⑳																				
セールスポイント																													
ルーム内薄汚れ				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換済</td> </tr> </table>						A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済																				
登録No.				月 日 までに変更できる方																									
車体番号				DKLFW-107829																									
FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨																				
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	車輪	傷																				