


2021 MAZDA CX-30 2.0 20S Proactive Touring Selection		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-DMEP	DISPLACEMENT 1,997 cc		
YEAR / REG. 2021/02	MILEAGE 12,286 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. DMEP-124986	DIMENSIONS (L X W X H) 439 × 179 × 154 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Mazda Harmonic Acoustics (8 speakers)		Power Tailgate 360° Camera Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Wheels have scratches. Interior is dirty, with scratches, burns, holes, scuffs, tears, and rips. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成32年2月		車名・グレード CX-30 20S ⁺ ロアアクティブ ⁺ ツーリング ⁺ セレクション		2WD 4WD		評価点 (4.5)	
ディーラー・並行 モデル年式 5BA-DMEP		型式 2000		ドア 5		定員 5人	
ハンドル 左・右		燃料 ガソリン		形状 HB		積載 kg	
車種 自家用		シフト CAT		セールスポイント (正常に機能するものに限りです)			
車検 年 月 (日)		冷暖 AAC		スマートキー・ETC			
走行 1万2千286 km		燃料 ガソリン		左右シートヒーター シートメモリー			
色 グレー		色コード 47C/EF2		諸備品 (純正品に限り○をつけてください)			
R券 9,720 円				(PS) (PW) (ABS) (エアB) (AW) SR ナビ TV カワ			
注意事項申告欄				新車保証書 有・無			
外装 小A・小U ホイール キズ 室内 汚れ							
フロントガラス キズ・ひび割れ・リペア跡・X要				A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
内装 キズ・ひび割れ・コゲ・穴・スレ・キレ・破れ				型式検査番号 19358			
車台番号 124986				車検区別番号 0051			
登録番号				全長 439 mm 全幅 179 mm 全高 154 mm			