

2021 MAZDA Mazda2 15C		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6BA-DJLFS	1,496 cc		
YEAR / REG.	MILEAGE		
2021/08	40,237 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Other		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DJLFS-738822	406 × 169 × 150 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Interior has odor and dirt, with scuffs on the headliner. Driver's seat shows moderate wear. Door trim has minor A-grade damage, pillar trim has moderate A-grade damage. Cargo area trim has moderate A-grade damage. Steering wheel and shift knob show wear. Left front door has repair marks, exterior touch-up paint marks, and thin line scratches. Small exterior scratches are present. Front bumper bottom has large A-grade damage. Front glass has minor stone chips, and wheel cover has A-grade damage.			

出品票		18995		0153		シブタス		評価点	
前年登録		車 年		月		グレード		 HONDA	
R 03		77972		5		15C			
8		型式 6BA-DJLFS		排気量 1,500 cc		燃料 90 軽油			
車種		車 年		車種		車種		車 年	
走行距離		4万 0千 2百 37 km		マイル (約換)		* (改ざん)		# (不明)	
外装色		7-ティック874ト		色 替無		カラーNo.		内装色	
車台No.		DJLFS-738822		色 替		色 替		色 替	
登録No.		抹消		リサイクル 済完全		8,140 円		未燃費	
5 ()		積載量		積込 量		406 cm		169 cm	
輸入のみのみ		輸入 国		ディーラー		走行 距離		150 km	
セルスルポイント		景像車		純正ナビ		マツダコネク		ユーティリティPKG	
景像車		純正ナビ		マツダコネク		ユーティリティPKG		Bカメラ	
LEDヘッドライト		ETC		電		電		電	
納結ミラー									

注意事項・不具合箇所

検査員記入欄：景像車「有」の場合は検査場所・交換場所を記入

室内臭い有室内汚れ有天蓋ずれ中

運転席ヘタリ中ドア内張A小ビラー内張A中

荷室内張A中ハンドルスレシフトノブずれ

左前ドア座席座墊外装ツツP除外装漆損傷

外装小キズ有Fバンパー下A大

Fガラス飛び石小ホイールカバーA