

2021 Nissan Roox HighwayStar Highway Star X		OVERALL		4.5
		EXTERIOR	INTERIOR	
		-	-	
MODEL CODE B44A		DISPLACEMENT 659 cc		
YEAR / REG. 2021/09		MILEAGE 10,361 km		
DOORS 5		SEATS 4		
DRIVETRAIN 2WD (FF)		TRANSMISSION AT		
FUEL Hybrid (Petrol)		STEERING Right		
EXTERIOR COLOR Black		BODY TYPE Kei		
CHASSIS NO. B44A-0076502		DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS				
Alloy Wheels Pre-Collision Braking Side Camera 360° Camera		Power Sliding Doors (Both Sides) (Drive... Front Camera Back Camera Navigation System		
INSPECTOR REPORT				
Tire cracks, medium seat stains, small steering wheel scuffs, minor exterior scratches, small seat wrinkles, small door trim scuffs, left quarter panel repair marks.				

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R3 / 9月	メーカー 日産	ドア数 5	ボディ形状 軽四	評価点 4.5
車名 ルークス	グレード ハイウェイスター X	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 B44A	登録区分 A・⑤・C	
年 8	月 9	日 10	走行 10,361 km	燃料 ガソリン
色 ブラックパール	カラーNo. ()	エアコン ()	安全装置 ()	装備品 ()
左・右 ()	ディーラー ()	走行 ()	価格 6,560円	オプション ()
セールスポイント CD/バックカメラ/ESC横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/メモリーナビ/パワーステアリング/V /衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ベンチシート/D V D再生/全周周知カメラ/フロントカメラ/サイドカメラ/両側電動スライドドア				
検査記入欄 タイヤヒビ シートしめ ハンドルのしめ 外装の傷 シートしめ ドア内装のしめ 左クワーター				
修復歴 有・⑥				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
月 日 まで B44A-0076502				
cm cm cm kg				