

2021 Nissan Serena 2.0 S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-C27	DISPLACEMENT 1,997 cc		
YEAR / REG. 2021/02	MILEAGE 37,000 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. C27-025850	DIMENSIONS (L X W X H) 469 × 170 × 187 cm		
SALES POINTS			
Cruise Control			
INSPECTOR REPORT			
Front windshield stone chips, wheel cover scratches, interior dirt, general scratches, cargo area minor issues, faulty A/C.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 2月	メーカー 日産	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 セレナ	グレード 2.0 S 送迎オートステップ 助手席スライドアップ	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 CC	型式 5BA-C27	通称 セリナ	内装 A・B
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ()	後付部品 (保証書・取扱説明書 等)	
走行 37,000 マイル	インパネ CVT			
外装色 ブリリアントシルバーメタリック	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ O印 を記入	
()	内装色 8 人	AW	サンルーフ	革シート
左・右 左・右	ディーラー 10,490円	ナビ	TV	その他
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/衝突被害軽減ブレーキ/スマートキー/盗難防止システム/オートクルーズコントロール/横滑り防止装置 (E S C) /3列シート/CD/全周囲カメラ/フロントカメラ/サイドカメラ/バックカメラ/障害物センサー/両側スライド片側電動ドア/福祉車両				
検査記入欄 フロントガラス飛石キズ ホイールカバー傷 内装汚れ 傷 荷室A エアコン不良				
修復歴 有 . ()				
登録No. C27-025850 月 日 までにも変更できる方				
シリアル No. C27-025850				
FW	トビ	傷A	フレ	外装
内装	シス	ヤブレ	コガ	コガ
小	ホイル	エアロ	シリアル	長さ
車種	長さ	幅	高さ	最大積載量
cm	cm	cm	cm	Kg