

2021 Peugeot 2008 Allure		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-P24HN05	DISPLACEMENT 1,199 cc		
YEAR / REG. 2021/03	MILEAGE 77,739 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. VR3USHNSSMJ544192	DIMENSIONS (L X W X H) 431 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Roof Rails Adaptive Cruise Control	
INSPECTOR REPORT			
Steering wheel wear, seat wear, trim A, oil seepage, minor exterior scratches (light A), interior dirt and wear.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R3 / 3月	メーカー プジョー	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 2008	グレード アリュール	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 1190 cc	型式 5BA-P24HN05	通称 4WD	内装 A・B・C
車検 10年3月 / 抹消	燃料 ガソリン	ディーゼル	後付部品 ()	登録区分 ()
走行 10万7千739km	シフト AT	AT	後付部品 ()	登録区分 ()
外装色 ホワイト	カラーNo. (0)	エンジン AG・AGD・WAG・()	後付部品のみ O印 を記入	登録区分 ()
内装色 ()	内装 ブラック	乗車定員 5人	PS	サンルーフ
走行 16,320km	走行 16,320km	走行 16,320km	ABS	ナビ
セールスポイント アクティブセーフティブレーキ 17インチAW				
検査記入欄 ハンドルスレ シートスレ トリムA オイル漏み 外装小傷、漏A				
修理履歴 有・無	A キズ B へこみ C 凹み D 色あせ E 汚れ F ガラスキズ W 経年劣化 S サビ C 腐食 X 交換 Y 交換済 Z 交換済 修理済 月 日 までに名実できる方 車検 VR3USHNSSMJ544192 シリアル No. 重量 0 kg			