

2021 LEXUS RX 300		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3BA-AGL20W	1,998 cc		
YEAR / REG.	MILEAGE		
2021/02	70,716 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Other		
CHASSIS NO.	DIMENSIONS (L X W X H)		
AGL20-0020490	489 × 189 × 171 cm		
SALES POINTS			
Alloy Wheels		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera		Navigation System	
Lexus RX Premium Sound System (12 s...			
INSPECTOR REPORT			
Interior trim scratches, light interior dirt, seat wrinkles, and minor exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

出品票

型式番号

19839

車両識別番号

0002

シリアル番号

年

月

日

車名

RX

グレード

300

年

月

日

車名

3BA-AGL20W

排気量

2,000 cc

燃料

ガソリン

駆動

FF

評価

4.5

車種

乗用車

年

月

日

車名

3BA-AGL20W

排気量

2,000 cc

燃料

ガソリン

駆動

FF

評価

4.5

走行距離

70,716 km

外装色

ソニックシルバー

カラーNo.

色替無

車台No.

AGL20-0020490

登録No.

抹消

定価

511,000円

輸入車

モーター

セーリングポイント

後席型 乗用車 純正12.3インチナビ フルセグ バックカメラ レクサスセーフティセンス アダプティブクルーズコントロール

純正装備品

○をつける

純正ナビ

SR

純正TV

SR

純正AW

エアロ

TV機能

フルセグ フルセグ アナログ

ナビ機能

フルセグ フルセグ アナログ

ナビ機能

フルセグ フルセグ アナログ

ナビ機能

フルセグ フルセグ アナログ

注意事項・不具合箇所

検査員記入欄：修理歴「有」の場合は修理箇所・交換箇所を記入

室内内装傷

室内汚れ

シートしわ

外装小傷あり

ドアミラー

キズ

ヒビ

ウレ

1点

2点

3点

4点