

2021 Subaru Levorg Levorg 1.8 GT		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 4BA-VN5	DISPLACEMENT 1,795 cc		
YEAR / REG. 2021/01	MILEAGE 22,995 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Station Wagon		
CHASSIS NO. VN5-007106	DIMENSIONS (L X W X H) 475 × 179 × 150 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Cruise Control	
INSPECTOR REPORT			
Exterior has minor abrasions and dents. Underbody has rust. Interior trim has scratches. Front windshield has scratches, stone chips, cracks, repair marks, and requires major repair or replacement. Interior has scratches, stains, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和3 1 月		車名・グレード レヴォーグ GT		2WD (4WD)		評価点 (4.5)	
ディーラー・並行 型式 4BA-VN5		排気量 1800		ドア 5		定員 5人	
モデル年式 年 ハンドル 左・右		形状 W		積載 kg		外装 内装 B B	
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限りです)			
車検 年 月 (日)		冷暖 AAC		スマートキー・ETC			
走行 2万2千995 km		燃料 ガソリン		ナビ TV パックカメラ			
色 シルバー		色コード G1U/J20		諸備品 (純正品に限り○をつけてください)			
R券 9,630 円				(PS) (PW) (ABS) (エアB) (AW) SR ナビ TV カワ			
注意事項申告欄				新車保証書 有・無			
外装 小A・小U							
下廻り サビ							
内張り キズ							
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要 内装 (キズ) 汚レ・コゲ・穴・スレ・キレ・破レ							
車台番号 007106				A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
登録番号				型式検査番号 検査 長さ 幅 高さ			