


2021 Suzuki Alto 5D L		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-HA36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/07	MILEAGE 28,138 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Kei			
CHASSIS NO. HA36S-619630	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
INSPECTOR REPORT			
No collision mitigation brake. Minor scratches on door mirror and trim. Stains on seats. Minor dirt on headliner. Dirt and tear on floor carpet.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 7月		メーカー スズキ		ドア枚数 5	ボディ形状 軽四	評価点 4																				
車名 アルト		グレード L	駆動区分 2WD 4WD																							
車歴 自用・その他 ()	排気量 650	型式 5BA-HA36S	通称 型式	内装 A・B・C																						
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)																							
走行 28,138 マイル	シフト AT																									
外装色 ホワイト	カラーNo. (26U)	エアコン	新備品のみ O印 を記入																							
()	内装色	乗車定員 4 人	P	P	AW	サンルーフ																				
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料	6,960 円	預託金																				
セールスポイント																										
検査記入欄			修復歴 有 ()																							
衝突被害軽減ブレーキなし、DミラーA、トリムA、シート汚れ、天張りヨゴレA、フロアカーペットヨゴレA、ブレ			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>				A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																	
登録No.			名義中																							
月 日			までに名義できる方																							
車体 番号			HA36S-619630																							
シリアル No.																										
PW	トビ	丸	ワレ	外装	小	ホイール	エアロ																			
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	丸																			
長さ	幅	高さ	最大積載量																							
cm	cm	cm	Kg																							