


2021 Suzuki Alto 5D L		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-HA36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/09	MILEAGE 35,580 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Kei			
CHASSIS NO. HA36S-626119	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
INSPECTOR REPORT			
Driver's mirror minor scratch, trim stains, seat stains and scuffs, headliner stains, floor carpet stains, signboard marks.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3		メーカー スズキ		ドア枚数 5		ボディ形状 軽四		評価点 4																					
9月		車名 アルト		グレード L		駆動区分 2WD 4WD																							
車歴 自用・その他 ()		排気量 650		型式 5BA-HA36S		通称 型式		内装 A・B・C																					
車検 - 年 - 月 / 日		燃料 ガソリン		ディーゼル		後日送り品 (登録書・取扱説明書 等)																							
走行 35,580		マイル		AT																									
外装色 ホワイト		カラーNo. 26U		エアコン		新備品のみ O印 を記入																							
()		内装色		乗車定員 4 人		P3 P4 AW サンルーフ 革シート																							
ハンド 左・右		輸入 区分		ディーラー		並行		リサイクル料 6,960円・預託金																					
セールスポイント ESC、ISS、AEB、デュアルセンサーブレーキサポート、車線逸脱警報、アイドリングストップ、D席シートヒーター																													
検査記入欄 Dミラー-A、トリムヨゴレ、シート汚れスレ、天張りヨゴレ、フロアカーペットヨゴレ、カンバンアト		修復歴 有 () <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・凹み</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・剥落</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>								A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
登録No.		名義中																											
月		日																											
車体 番号		HA36S-626119																											
シリアル No.																													
FW トヨタ		フレ		外装 A・B		ホイール A・B		エアロ																					
内装 ヨゴレ		シミ		ヤブレ		コゲ		コゲ穴																					
オーディオ穴		穴		穴		穴		穴																					
長さ cm		幅 cm		高さ cm		最大積載量 Kg																							