

2021 Suzuki WagonR FA		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-MH85S	DISPLACEMENT 657 cc		
YEAR / REG. 2021/03	MILEAGE 23,783 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Kei			
CHASSIS NO. MH85S-116391	DIMENSIONS (L X W X H) 340 × 148 × 165 cm		
INSPECTOR REPORT			
Back panel dent, minor scratches on driver's mirror and trim, seat and floor carpet stains, dashboard adhesive residue. No Safety Support or pre-collision braking system.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3		メーカー スズキ		ドア枚数 5		ボディ形状 軽四		評価点 3.5																					
3月		車名 ワゴン R		グレード F A		駆動区分 2WD 4WD																							
車歴 自家用・その他(レンタカー)	排気量 650	型式 CC	5BA-MH85S		通称 型式	内装 A・B・C																							
車検 9年3月	抹消	燃料 ガソリン	ディーゼル	後日送り品(保証書・取扱説明書等)																									
走行 23,783マイル	インパネ	AT																											
外装色 ホワイト	カラーNo. (26U)	エアコン	新備品のみ O印 を記入																										
()	色変更はO印に 「色変」と記入	内装色	乗車定員 4人	P3	P4	AW	サンルーフ	革シート																					
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料 6,470円	預託料	エディック	ASB	ナビ	TV																				
セールスポイント ESC				修復歴 有 (5)																									
検査記入欄 バックパネル歪、DミラーA、トリムA、シートヨゴレスレ、ダッシュノリ・ノリ跡、フロアカーペットヨゴレ、セーフティサポート非装着車、衝突被害軽減ブレーキなし				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>						A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
登録No.				名義中																									
月				日																									
車体 番号				MH85S-116391																									
シリアル No.																													
PW	トビ	丸	ワレ	外装	小	ホイール	エアロ																						
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	丸	長さ	幅																				
				高さ		最大積載量		Kg																					