

2021 Suzuki WagonR FA		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-MH85S	DISPLACEMENT 657 cc		
YEAR / REG. 2021/03	MILEAGE 27,480 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Black		
BODY TYPE Kei			
CHASSIS NO. MH85S-116853	DIMENSIONS (L X W X H) 340 × 148 × 165 cm		
INSPECTOR REPORT			
No safety support or collision mitigation braking. Minor scratches on door mirrors and trim. Seat scuffs and minor damage in the cargo area.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 3月		メーカー スズキ		ドア枚数 5	ボディ形状 軽四	評価点 4																				
車名 ワゴンR		グレード FA		駆動区分 2WD 4WD																						
車歴 自家用・その他(レンタカー)	排気量 650	型式 5BA-MH85S	通称 型式	内装 A・B・C																						
車検 9年3月 / 抹消	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)																							
走行 27,480 km	マイル インパネ	AT																								
外装色 ブラック	カラーNo. (ZJ3)	エアコン (A)	整備品のみ O印 を記入																							
()	色変更はO印に 「色変」と記入	内装色	乗車定員 4人	P	AW	サンルーフ																				
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料 6,470円	預託料	エディック																				
セールスポイント ESC			修復歴 有 (5)																							
検査記入欄 セーフティサポート非装着車、衝突被害軽減ブレーキなし、DミラーA、トリムA、シートスレ、荷室内A			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・剥落</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>				A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・剥落	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・剥落	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																	
登録No.			名義中																							
月 日			まで(に)名義できる方																							
車体 番号 MH85S-116853																										
シリアル No.																										
PW	トビ	フ	外装	小	ホイール	エアロ																				
内装	シ	ヤ	コ	コ	オー	最大積載量																				