

2021 Toyota Corolla Axio EX		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-NRE161	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/09	MILEAGE 20,663 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Sedan		
CHASSIS NO. NRE161-0099065	DIMENSIONS (L X W X H) 440 × 170 × 146 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior trim scratches, minor seat scuffs, touch-up paint marks, wheel cover A.			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 9月		メーカー トヨタ		ドア枚数 4	ボディ形状 セダン	評価点 4.5																				
車名 カローラアクシオ EX		グレード	駆動区分 2WD	4WD																						
車種 自家用 ・ その他 ()	排気量 1500 cc	型式 5BA-NRE161	通称 型式	内装 A ・ ⑨ ・ C																						
車検 年 月 日	燃料 ガソリン	ディーゼル	後日送り品 (保証書 ・ 取扱説明書 等)																							
走行 20,663 km	シフト AT	登録区分																								
外装色 ホワイト	カラーNo. 040	エアコン	新車品のみ ○印 を記入																							
内装色	乗車定員 5 人	⑨	⑨	AW	サンルーフ	革シート																				
ハンドル 左 ・ ⑨	輸入 区分	ディーラー	並行	⑨	⑨	⑨																				
9,470 円		⑨	⑨	⑨	TV	キーレス																				
セールスポイント																										
検査記入欄		修復歴 有 ・ ⑨																								
室内内張傷、シートすれ小、タッチP跡、ホイールカバーA		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No.		名義中																								
月 日		までに名義できる方																								
車検番号 NRE161-0099065																										
FW ⑨	備A	ワレ	外装 小	ホイール	エアロ	シリアル No.																				
内装 ⑨	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	⑨																				
長さ cm	幅 cm	高さ cm	最大積重量 kg																							