


2021 Toyota Corolla Axio EX		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-NRE161	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/03	MILEAGE 26,400 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Sedan		
CHASSIS NO. NRE161-0094104	DIMENSIONS (L X W X H) 440 × 170 × 146 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Sun visor torn, various scratches and dents			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 3月		メーカー トヨタ		ドア枚数 4		ボディ形状 セダン		評価点 4																					
車名 カローラアクシオ		グレード EX		駆動区分 2WD 4WD																									
車種 自家用・その他 ()	排気量 1500 cc	型式 5BA-NRE161	通称 型式	内装 A・⑨・C																									
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																										
走行 26,400 km	シフト フロア	AT																											
外装色 シルバー	カラーNo. ()	エアコン ④⑤・AAG・WAG・()	新着品のみ 〇印 を記入																										
内装色 ()	乗車定員 5 人	④⑤	④⑤	AW	サンルーフ	革シート																							
左・右 左・右	輸入 区分	ディーラー	並行	ナサイクル料 9,470 円	預託金	④⑤	④⑤	④⑤	TV																				
セールスポイント スマートキー★スペアキー★ナビ★プッシュスタート★ オートハイビーム★																													
検査記入欄 サンバイザー切れ 各傷凹				修復歴 有・⑨ <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>						A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
登録No. NRE161-0094104				名義中 月 日 までに名義できる方																									
車検 NRE161-0094104																													
FW	トビ石	傷A	ワレ	外装	小	ホイル	エアロ	シリアル No.																					
内装	ヨレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	④⑤	長さ	440 cm																				
							幅	169 cm																					
							高さ	146 cm	最大積重量 Kg																				