

2021 Toyota Corolla Axio EX 4WD ECVT		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-NZE164	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/08	MILEAGE 117,605 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Sedan		
CHASSIS NO. NZE164-7084443	DIMENSIONS (L X W X H) 440 × 169 × 148 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Interior dirt, scratches, scuffs, engine compartment condition C, worn carpet, exterior discoloration C.			

ORIGINAL JAPANESE AUCTION SHEET

車種名	カローラ アクシオ	グレード	EX 4WD ECVT	評価点
初年度登録	2021年08月	燃料	ガソリン	4
認定型式	3BA-NZE164	シフト	AT	
車台番号	NZE164-7084443	走行距離	117,605km	内装評価点
排気量	1,500cc	系統色	白	C
駆動	4WD	車検	車検期限 年 月	
リサイクル料	9,470円	車歴	自家用	
		乗車定員	5	
		ドア枚数	-	

コアサポート

ロアサポート

バンパーホースメント

サイドメンバー突起部

クロスメンバー

サイドメンバー

インサイドパネル

フロア (キャブ床)

ビラーインナー

ダッシュパネル

センターフロア

ルーフパネル

サイドシルインナー

フロアサイドメンバー

セットバック(キャブ背)

ビラーインナー

トランクフロア

インサイドパネル

サイドメンバー

クロスメンバー

バックパネル

バンパーホースメント

下回り

特殊

フォグ

ヘッドライト

ウィンカー

アウターミラー

サイドウィンドー

テールランプ

バンパーランプ

フォグ

ヘッドライト

ウィンカー

アウターミラー

サイドウィンドー

テールランプ

バンパーランプ

■特記事項

書類送付は成約後10日前後からります

車内汚れ・スレ・キズ エンジンルームC カーベツスリキレ 外装変色C

U、D：押され/曲がり/歪み