


2021 Toyota Corolla Fielder EX		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-NRE161G	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/08	MILEAGE 31,267 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Station Wagon		
CHASSIS NO. NRE161-0097708	DIMENSIONS (L X W X H) 440 × 170 × 148 cm		
SALES POINTS			
Roof Rails		Pre-Collision Braking	
INSPECTOR REPORT			
Interior trim scratches, wheel cover A			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 8月		メーカー トヨタ		ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4.5																				
車名 カローラフィールダー		グレード EX		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 1500 cc	型式 5BA-NRE161G	通称 型式	内装 A・⑨・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)																							
走行 31,267 km	シフト AT																									
外装色 ホワイト	カラーNo. (040)	エアコン	新着品のみ ○印 を記入																							
()	内装色	乗車定員 5 人	PS	PS	AW	サンルーフ																				
ハンドル 左・右	輸入 区分	ディーラー	並行	ナビ	TV	キーレス																				
セールスポイント ルーフレール																										
検査記入欄 室内内張傷、ホイールカバー A		修復歴 有・⑨																								
		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
		登録No. _____ 月 _____ 日 までに名義できる方 名義中 車検番号 NRE161-0097708																								
FW	トビ	備A	フレ	外装	小	ホイール	エアロ	シリアル No.																		
内装	ヨコ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	⑨	長さ cm	幅 cm																	
								高さ cm	最大積載量 kg																	