

2021 Toyota COROLLA TOURING Hybrid Double V		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZWE211W	DISPLACEMENT 1,797 cc		
YEAR / REG. 2021/04	MILEAGE 25,669 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Station Wagon		
CHASSIS NO. ZWE211-6074445	DIMENSIONS (L X W X H) 450 × 175 × 146 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Exterior: Significant scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. Frame: No structural damage.			

ORIGINAL JAPANESE AUCTION SHEET

青森県内のカー鑑定/JAAA鑑定証の発行と下記記載の評価は真となります

車種 R3 4月	メーカー トヨタ	ドア数 5	ボディ形状 ステーションワゴン	評価点 3.5
車名 カローラツーリング	グレード ハイブリッド	ダブルバイビー		
用途 自家用	右	ZWE211W	1800	ガソリン
年 2021	月 4	日 25	マイル 25,669	AC
カラー ブラックマイカ	カラーNo. ()	リサイクル料 9,440円	販売店 ZWE211-6074445	
シフト フロア	AT	5人	長さ cm	幅 cm

車検返却日
(保証書・取説説明書等)

整備
エンジン
変速機
サスペンション
ブレーキ
その他

バックカメラ/TC/運転席エアバッグ/スマートキー/キーレスエントリー/A B S/助手席エアバッグ/モータービッドフルセグTV/衝突被害軽減ブレーキシートヒーター

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが低いほど、車体の状態が良いことを示します。ダメージレベルが高いほど、車体の状態が悪いことを示します。ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが低いほど、車体の状態が良いことを示します。ダメージレベルが高いほど、車体の状態が悪いことを示します。

クオリティグレード説明
外装: 劣化するボディパネルは補修済みですが、小さなボディパネルが残っています。
内装: 劣化する汚れ等が、部分的にあります。
機体: 劣化する機体には異状はありません。

車検返却の保証は、停止状態で実施できる範囲で行っています。