

2021 Toyota Hiace Van DX GL Package		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE TRH200V	DISPLACEMENT 1,998 cc		
YEAR / REG. 2021/03	MILEAGE 53,919 km		
DOORS 5	DRIVETRAIN 2WD (FR)		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Minivan			
CHASSIS NO. TRH200-0337538	DIMENSIONS (L X W X H) 470 × 170 × 199 cm		
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains and dirt are present. Repair History: No abnormalities in the structural components.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なりです

初年度登録 R3/3月	メーカー トヨタ	ドア数 5	ボディ形状 バン	評価点 4
車名 ハイエースバン	グレード DX GLパッケージ			
車種 自家用	形式 TRH200V	年式 2000	燃料 ガソリン	内装 B
車検 -年-月/日	走行 53,919 km	駆動 2WD	エンジン AC	重量 Kg
外装色 ホワイト	カラーNo. ()	リサイクル料 9,550円	備付番号 TRH200-0337538	
()	シフト フロア	AT	長さ cm	幅 cm
後日送り品 (保証書・取扱説明書等)	車庫状態の説明			
装備 CD/バックカメラ/ETC/運転席 エアバック/キーレスエント リー/ABS/助手席エアバッ ク/衝突被害軽減ブレーキ/衝 突安全ボディ 査定員記入欄	車庫状態の説明 小 カードサイズ未満 中 A4サイズ未満 大 A4サイズ以上 数値 金額以上 タイヤ磨損は磨耗の程度を数値により判定しています。(※リヤ車ではありません) 【例】前 5分は1〜磨耗50%程度 程度を示す			
※ダメージレベルに関する注意事項 傷は記号のみ 小は1 中は2 大は3 例 さす 傷ハ ⇒ A へこみ 小 ⇒ U1 さす 傷 ⇒ A2 さす へこみ 大 ⇒ A3	車庫状態の確認は、停止状態で実施できる範囲で行っています。			
外装: 気になるキズやへこみは補修済みですが、小さなキズやへこみが残っています。 内装: 気になる汚れ等が、部分的にあります。 修復歴: 骨格部位に異常はありません。				