

|                                                                                                                                              |                        |          |          |
|----------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------|----------|
| 2021 Toyota Passo 1.0 Moda                                                                                                                   |                        | OVERALL  |          |
|                                                                                                                                              |                        | 4        |          |
|                                                                                                                                              |                        | EXTERIOR | INTERIOR |
|                                                                                                                                              |                        | -        | -        |
| MODEL CODE                                                                                                                                   | DISPLACEMENT           |          |          |
| 5BA-M700A                                                                                                                                    | 996 cc                 |          |          |
| YEAR / REG.                                                                                                                                  | MILEAGE                |          |          |
| 2021/01                                                                                                                                      | 65,000 km              |          |          |
| DOORS                                                                                                                                        | SEATS                  |          |          |
| 5                                                                                                                                            | 5                      |          |          |
| DRIVETRAIN                                                                                                                                   | TRANSMISSION           |          |          |
| 2WD (FF)                                                                                                                                     | AT                     |          |          |
| FUEL                                                                                                                                         | STEERING               |          |          |
| Petrol                                                                                                                                       | Right                  |          |          |
| EXTERIOR COLOR                                                                                                                               | BODY TYPE              |          |          |
| Brown                                                                                                                                        | Hatchback              |          |          |
| CHASSIS NO.                                                                                                                                  | DIMENSIONS (L X W X H) |          |          |
| M700A-0182728                                                                                                                                | 368 × 167 × 153 cm     |          |          |
| SALES POINTS                                                                                                                                 |                        |          |          |
| Pre-Collision Braking                                                                                                                        |                        |          |          |
| INSPECTOR REPORT                                                                                                                             |                        |          |          |
| Front glass: Scratches, stone chips, cracks, repair marks, replacement required. Interior: Scratches, dirt, burn holes, scuffs, tears, rips. |                        |          |          |

[illegible]