

2021 Toyota Passo Moda G Package		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-M700A	DISPLACEMENT 996 cc		
YEAR / REG. 2021/03	MILEAGE 42,604 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE Hatchback		
CHASSIS NO. M700A-0185109	DIMENSIONS (L X W X H) 368 × 167 × 153 cm		
SALES POINTS			
Alloy Wheels Navigation System		Pre-Collision Braking	
INSPECTOR REPORT			
Light interior dirt			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 3月		トヨタ		5		コンパクトハッチバック		4																					
パスン		モーダ Gパッケージ		シ		4WD																							
車種	白身用・その他 ()	排気量	1000 CC	型式	5BA-M700A	通称		内装	A・B・C																				
車検	10年3月 / 抹消	燃料	ガソリン	ディーゼル		後日選り品 (色選り・取扱説明書 等)																							
走行	42,604 km	インパネ	AT																										
外装色	グリーンII (XE3)	エアコン	AG・AG・WAG ()	装備品のみ O印 を記入																									
内装色		乗車定員	5人	サンルーフ	車シート																								
左・前	ディーラー・運行	リサイクル料	8,190円	ナビ	TV	キーレス																							
セールスポイント ★ワンオーナー★スマートアシスト★パナソニック9インチナビ★フルゼグ★スマートキー★プッシュスタート★LEDヘッドライト★ETC★アイドリングストップ★クリアランスソナー★																													
検査記入欄 ルーム内薄汚れ																													
修復歴 有・無																													
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換時</td> </tr> </table>										A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時
A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時																				
登録No. _____ 月 _____ 日 _____ までに変更できる方																													
車体番号 M700A-0185109																													
車種 _____ 年 _____ 月 _____ 日 _____ 最大積載量 _____ kg																													