

2021 Toyota Roomy 1.0 X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2021/07	MILEAGE 36,287 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. M900A-0574082	DIMENSIONS (L X W X H) 370 × 167 × 173 cm		
SALES POINTS			
Pre-Collision Braking Navigation System		Back Camera	
INSPECTOR REPORT			
Screwed lower support U, sign marks, light scratches on exterior, finish marks, underbody A/U, small tears/rips on seats, interior trim damage, interior dirt, mirror A.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号 19834	車両種別番号 0001	シリアル番号	評価点	
年式 R 03	車名 ムービー	ドア数 5	グレード 1.0 X	駆動 4WD	4	
月 7	型式 5BA-M900A	排気量 1,000 cc	燃料 ガソリン	軽油	内装 A B C	
車種 乗用車	年 2021	月 7	車体 白	シフト CVT	変速機 AC	
走行距離 36,287 km	色 パールホワイトIII	色 色替無	カラーNo. (交差) (改ざん) (不明)	内装 色	純正装備品 ○をつける	
車台No. M900A-0574082	登録No. 抹消	リサイクル 9,130円/月	未償還	純正ナビ	純正TV	
定員 5人	乗車数 5人	長さ 370 cm	幅 167 cm	高さ 173 cm	純正AW	純正シート
輸入車のみ モデル 年式	輸入区分 ディーラー	走行 ハンドル	左	右	純正AW	純正シート
セールスポイント 禁煙車/ナビ/Bカメラ/両側電動/						
注意事項・不具合箇所						
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入 ネジ止アサポートU、看板跡 外装うすい線キズ、仕上げ跡 下廻りA、U シート切れ、破れ小 室内内張傷 室内汚れ、ミラーA						
ドアミラー 上角	キズ 無	ヒビ シヤッキ	フレ 無			