

2021 Toyota Roomy Custom 1.0 Custom G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2021/12	MILEAGE 23,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. M900A-0639876	DIMENSIONS (L X W X H) 371 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control	
INSPECTOR REPORT			
Front glass has scratches, stone chips, cracks, and repair marks; replacement is required. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和3 12 月	車名・グレード ルーミー カスタムG	2WD 4WD	評価点 (R)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 5BA-M900A	排気量 1000 CC	ドア 5 形状 V
定員 5人	積載 kg	外装 B	内装 B
車歴 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)	冷房 AC	キーレススマートキー★ETC★バックモニター	
走行 2万3千000 km	燃料 ガソリン	装備品 (純正品に限り○をつけてください)	
色 ブラック	色替 色コード X07	(PS) (PW) (AB) (TB) AW	
R券 9,130 円		SR ナビ TV カワ	
注意事項申告欄	センターピラー修正	新車保証書 有・無	後日品
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	スア	
車台番号 0639876		A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
登録番号		型式指定番号 参考	類別区分番号 参考