

2021 Toyota Roomy Custom Custom G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2021/12	MILEAGE 20,371 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. M900A-0634959	DIMENSIONS (L X W X H) 371 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Right center pillar repaired, left front pillar hinge area dent, exterior linear scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 12月	メーカー トヨタ	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価値 R
車名 ルーミー	グレード カスタムG	駆動区分 2WD 4WD		
車歴 自家用・その他 ()	排気量 1000 cc	型式 M900A	通称 形式	内装 A・⑥・C
車検 8年12月 / 抹消	燃料 ガソリン	ディーゼル	後日選り込み (保証書・取扱説明書 等)	
走行 20,371 km	シフト フロア	AT		
外装色 ブラックマイカメタリック (X07)	カラーNo.	④D・AAG・WAG・ ()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	⑤	⑥	⑦
⑧ 左・⑨ 右 ⑩ 左・⑪ 右	⑫ 左・⑬ 右 ⑭ 左・⑮ 右	⑯ 左・⑰ 右 ⑱ 左・⑲ 右	⑳ 左・㉑ 右 ㉒ 左・㉓ 右	㉔ 左・㉕ 右 ㉖ 左・㉗ 右
セールスポイント				
ワンオーナー 両側パワースライドドア 純正ナビ フルセグ/Bluetooth 衝突軽減ブレーキ/レーンアシスト レーダークルーズコントロール クリアランスソナー LEDヘッドライト				
検査記入欄				
右センターピラー修理 左Fピラーヒンジ部凹み 外装線傷				
修理歴 ① 無				
A ネズ U ヘッドサマシ B キズ・ヘコ P 色あせ・サケ Q ガラスキズ W 補修品 S サビ C 腐食 X 交換品 YX 交換品 登録No. 月 日 までに名義できる方 車体番号 M900A-0634959				
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺